

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

*Replacement Sheet*

USSN 10/068,235  
For: Encoder-Based Control of  
Printhead Firing in a Label Printer  
Atty. Docket No. WHB-31573



1 / 12




FIG. 1




FIG. 10





FIG. 2





FIG. 3



4 / 12




FIG. 5







FIG. 6





6 / 12

FIG. 7





FIG. 11a




FIG. 11b

7 / 12





FIG. 8c



8 / 12




FIG. 9a





FIG. 9b

FIG. 9c



9 / 12

FIG. 12a





FIG. 12b





10 / 12




FIG. 12c




FIG. 12d

*Replacement Sheet*

USSN 10/068,235  
 For: Encoder-Based Control of  
 Printhead Firing in a Label Printer  
 Atty. Docket No. WHB-31573




FIG. 13



*Replacement Sheet*

USSN 10/068,235  
For: Encoder-Based Control of  
Printhead Firing in a Label Printer  
Atty. Docket No. WHB-31573

12 / 12




FIG. 14